

decision).

- Inadequate supervision was available for this task since supervisor was in charge of 30 scaffolders that were also in another area.
- On-the-job training for scaffold crews inadequate.
- Planning and coordination of adjacent work activities inadequate between supervisors.

Выводы/План действий

- Необходимо провести оценку занятых на лесах работников (как опытных, так и новичков) на предмет прохождения обучения и сертификации.
- Все работники должны знать, что при изменении обстановки работу следует приостановить и обсудить ее дальнейшее выполнение с бригадирами, прежде чем приступить к ней снова.
- Бригадиры должны проводить ежедневные (до выхода на площадку) проверки укомплектованности работников страховочными поясами с двойными стропами и оценку их (поясов) состояния.
- Наладить планирование работ с целью обеспечения ежедневного взаимодействия между строительными бригадами для определения параллельно выполняемых работ и принятие необходимых мер безопасности.
- Бригадиры различных специальностей должны ежедневно координировать работы таким образом, что бы обеспечить отсутствие людей в местах, находящихся в непосредственной близости от лесов в то время, когда на них выполняются какие-либо работы.
- Руководители и сотрудники отдела ТБ должны обходить свои объекты до начала работ с целью обнаружения потенциальных опасностей и путей их предупреждения. Полученная информация будет заноситься в форму, после чего будет обсуждаться в коллективах до выхода на площадки.

Lessons Learned /Action Plan

- Evaluate all new and existing scaffolders to determine their level of skill, knowledge and training certificates.
- Reinforce to all employees that when circumstances change work must stop and the work activities to be reviewed with their respective supervision before work recommences.
- Foremen must carry out daily pre-work checks to ensure that all scaffolders have the proper PPE prior to initiating work.
- Planning system to be improved to ensure different disciplines will communicate with each other on a daily basis to ensure that work at height to be carried out above other work crews is identified and proper precautions taken.
- Management to review their current & work permit system to focus on craft disciplines by area.
- Foremen and Safety Officers to walk through their work locations prior to the start of work activities and identify work related hazards and safety precautions. The obtained information will be recorded and then communicated, discussed by the respective work crews prior to work commencing.

SUPERVISORS/IN CHARGES OF OUR COMPANY AT VARIOUS WORK SITES ARE REQUESTED TO INCLUDE THIS BULLETIN IN THEIR WEEKLY MEETINGS AND THUS PROMOTE A SAFE WORKING CULTURE AMONG OUR WORK FORCE!

Супервайзерам и руководителям нашей компании, работающих на различных объектах. Просим вас добавить этот бюллетень в ваши еженедельные собрания по Технике Безопасности, что бы таким образом повысить совершенствование техники безопасности в работе среди наших работников!

Remember – Safety First!!!
Помните – Безопасность прежде всего!!!